IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of

U.S. Patent No. : 7,740,250 B2 Issued : June 22, 2010

Title : LIGHT VEHICLE COMPRISING A SWING AXLE

Docket No. : THP 0001 PA/36043.1

Certificate of Corrections Branch

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 EFS Web Electronic Submission December 14, 2010

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION FOR PTO MISTAKE UNDER 35 U.S.C. 254 and 37 C.F.R. 1.322

In the matter of U.S. Patent No. 7,740,250 B2, it is respectfully requested that a Certificate of Correction be issued to cover the following errors which occurred in the printing of the patent.

Col 5, Line 8, "dip" should read as -- clip --

Col 5, Line 51, "dose" should read as -- close --

REMARKS

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. All of the above errors occurred during the printing of the patent and, therefore, no fee is due.

Respectfully submitted, DINSMORE & SHOHL LLP

By: /Susan M. Luna/ Susan M. Luna

Registration No. 38,769

One Dayton Centre One South Main St., Suite 1300 Dayton, Ohio 45402-2023 Telephone: (937) 449-6400

Facsimile: (937) 449-6405

SML/jkw Encl.

268827_1